Marion Road and Sir Donald Bradman Drive Intersection Upgrade





Demolition works

The Australian and South Australian governments have committed \$85 million (50:50) towards an upgrade of the intersection of Marion Road and Sir Donald Bradman Drive.

Demolition works to facilitate the intersection upgrade are continuing.

What's happening:

Demolition works on the corner of Sir Donald Bradman Drive and Marion Road are continuing to help prepare the area. This will now include the northeastern corner of the intersection, which will commence in mid-August 2024, see map overleaf.

How this affects you:

Marion Road and Sir Donald Bradman Drive intersection will continue to remain open to traffic and pedestrians at all times. Variable speed and lane restrictions will be in place in the vicinity of the works.

Prior to the next stage of demolition works starting, temporary fencing will be installed around the property.

A hazard assessment will also be completed prior to demolition and any identified hazards will be removed. All hazardous material removal works will be carried out by a licensed contractor in accordance with the Environment Protection Authority Guidelines. These measures will ensure the safety of the community and workers.

Some disturbance can be expected such as noise, dust and vibration associated with the demolition and removal of structural elements, supporting foundations and hardstand areas but we will ensure we minimise these impacts as much as possible.

Pedestrians and cyclists are advised to take care when moving through the area. For safety reasons there may be some restricted access, onsite signage and traffic controllers will be in place to assist.

We will contact properties adjacent to, or directly impacted by the works, with location-specific information and expected timeframes before works commence.

When

Monday 12 August to mid October 2024, weather permitting

Hours of operation

7am to 6pm Monday to Saturday

Where

Corner of Sir Donald Bradman Drive and Marion Road, Cowandilla (see map overleaf)

Marion Road and Sir Donald Bradman Drive Intersection Upgrade Reference Number: #21841888 2/08/2024 Page 1 of 2

All road users

Please be aware of additional truck and large vehicle movements around the intersection and work zone. Plan ahead, allow extra travel time and take extra care when workers are on site.

Work map



In the event these works need to be rescheduled due to weather conditions or other circumstances outside of our control, we will advise you as soon as we have details.

We appreciate your cooperation whilst these important works are undertaken.

For further information:

- Visit <u>www.dit.sa.gov.au/MARIONSDB</u>
- Email <u>DIT.MarionSDB@sa.gov.au</u>
- Call 1300 794 880
- Scan the QR code to subscribe for project updates

