



In reply please quote 2019/15492/01

Mr Blair Boyer MP
Member for Wright
PO Box 1111
GOLDEN GROVE VILLAGE SA 5125

**PEOPLE AND BUSINESS
DIVISION**

77 Grenfell Street
Adelaide SA 5000

GPO Box 1533
Adelaide SA 5001

Telephone: 08 8343 2222
Facsimile: 08 8204 8740

ABN 92 366 288 135

Dear Mr Boyer,

**NOTICE OF DETERMINATION - REQUEST FOR ACCESS TO DOCUMENTS
UNDER THE FREEDOM OF INFORMATION ACT 1991**

I refer to your application made under the *Freedom of Information Act 1991* (the Act) which was received by the Department of Planning, Transport and Infrastructure on 11 November 2019.

You have requested access to:

"All documents relating to the fortnightly road maintenance and safety checks carried out by or for the Agency on McIntyre Road. From 1 January 2019 to date."

I have determined that access to all in scope information is granted and a copy is enclosed.

In accordance with Premier and Cabinet Circular PC045, if you are given access to documents as a result of this FOI application, details of your application, and the documents to which access is given, will be published in the agency's disclosure log within 90 days from the date of this determination. Any private information will be removed. A copy of PC045 can be found at <http://dpc.sa.gov.au/what-we-do/services-for-government/premier-and-cabinet-circulars>. If you have any objection to this publication, please contact us within 30 days of receiving this determination.

Attached is an explanation of the provisions of the Act which details your rights to review this determination, and the process to be followed.

Should you have any enquiries concerning your application please contact
[redacted] Freedom of Information Officer, [redacted]

Yours sincerely

[redacted]

Sam Rodrigues
Accredited Freedom of Information Officer

26 November 2019

RELEASED UNDER FOI ACT

YOUR RIGHTS TO REVIEW

INTERNAL REVIEW

If you are dissatisfied or concerned with the decision of this Agency regarding access to documents or the request for amendment to your personal records, you can apply for an Internal Review of that decision.

To apply for an Internal Review you must write a letter addressed to the Principal Officer or lodge an Internal Review application form with the Principal Officer of this Agency. The legislated application fee must accompany all applications, unless the fee was waived in the original Freedom of Information application, in which case there would be no fee payable for the application. The application must be lodged within 30 days after being notified of the decision.

The Agency will undertake the Internal Review and advise you of its decision within 14 days of receipt of the application.

Where the decision was made by the Minister or Principal Officer of the Agency, you are unable to request an Internal Review but you can apply for an External Review by the Ombudsman, or the South Australian Civil and Administrative Tribunal.

You are unable to apply for an Internal Review regarding a decision to extend the time limit for dealing with an application but you can apply for an External Review.

EXTERNAL REVIEW BY THE OMBUDSMAN

If the Agency does not deal with your Internal Review application within 14 calendar days (or you remain unhappy with the outcome of the Internal Review) you are entitled to an External Review by the Ombudsman SA.

You may also request an External Review by the Ombudsman if you have no right to an Internal Review.

The application for review by the Ombudsman should be lodged within 30 days after the date of a determination. The Ombudsman's Office, at their discretion, may extend this time limit.

Investigations by the Ombudsman are free. Further information is available from the Office of the Ombudsman by telephone on 8226 8699 or toll free 1800 182 150 (within SA).

APPEAL TO THE SOUTH AUSTRALIAN CIVIL AND ADMINISTRATIVE TRIBUNAL (SACAT)

If you are still dissatisfied with the decision made by this Agency after an Internal Review or after a review by the Ombudsman, you can request a review from SACAT.

You must exercise your right of review to SACAT within 30 calendar days after being advised of the determination or the results of any other Internal or Ombudsman Review. Any costs will be determined by SACAT, where applicable. For more information, contact;

South Australian Civil and Administrative Tribunal (SACAT)

Phone: 1800 723 767

Email: sacat@sacat.sa.gov.au

SCHEDULE OF DOCUMENTS - FREEDOM OF INFORMATION APPLICATION NUMBER

2019/15492/01

Document Number	Description of Document	Date of Document	Author	Determination Release / Refuse Access	Schedule Clause Applied
1	McIntyre Road	11-November-2019	DPTI	Release	N/A

RELEASED UNDER FOIA ACT

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
156306	-34.79687	138.65548	5405	L	L1	FS	1	Item	17/01/2019	Bridge Rd ASN needs replacing, letters peeling off (SI-Sign Defective (FS SP))
156533	-34.80826	138.67096	5405	L	L1	PN	14	Square Metre	12/06/2019	7 m x 2m Digout (PV-Digout - Depression (PN RT))
156545	-34.80279	138.66221	5405	L	L1	PJ	24	Square Metre	4/03/2019	6m x 4m Digout R2 (PV-Digout - Depression (PJ SP))
156559	-34.79899	138.6583	5405	L	L1	PN	6	Square Metre	12/06/2019	3 x 2m Digout (PV-Digout - Depression (PN RT))
156580	-34.79886	138.65805	5405	L	L1	PN	6	Square Metre	12/06/2019	3 x 2m Digout (PV-Digout - Depression (PN RT))
175375	-34.80875	138.67219	5405	R	R2	PJ	227.5	Square Metre	16/09/2019	65m x 3.5m at 80mm deep patch on McIntyre Road (PV-Digout - Depression (PJ SP))
186990	-34.80168	138.66107	5405	L	L1	PF	50	Metre	2/07/2019	Crack sealing required (PV-Crack Sealing (PF RT))
186992	-34.80636	138.66752	5405	L	L1	FR	1	Item	5/09/2019	ASN lettering falling off (SI-Sign Damaged/Fix (FR RT))
186997	-34.80968	138.67372	5405	L	L1	RR	1	Item	18/01/2019	Needs sight clearance (MT-Vegetation Control (RR SP))
187019	-34.83351	138.68045	5405	L	L1	DR	2	Metre	20/08/2019	2m kerb needs replacing (DR-Elements Collapsed (DR SP))
187029	-34.81643	138.67664	5405	L	L1	DR	1	Metre	20/08/2019	1m kerb lifting affecting drain (DR-Elements Collapsed (DR SP))
187032	-34.81474	138.67592	5405	L	L1	DR	1	Item	18/01/2019	Ever level lid needs replacing (DR-Elements Collapsed (DR SP))
187774	-34.7976	138.65675	5405	L	L1	LC	1	Item	24/09/2019	Chamber missing Inner cap (PV-Low Casting (LC SP))
187990	-34.80395	138.66402	5405	L	L1	PK	1	Metre	20/08/2019	Cracking on left lane 50 meters before Bayview drive approx 10meters long 4meters wide (PV-Crocodile Cracking (PK SP))
188077	-34.80815	138.67068	5405	L	L1	PS	1	Square Metre	29/01/2019	Washed out behind kerbing (SH-Shoulder Low (PS RT))
188090	-34.80864	138.67203	5405	L	L1	PJ	640	Square Metre	9/09/2019	Cracking and depression 80 meters buy 8 meters (PV-Digout - Depression (PJ SP))
188373	-34.82733	138.6798	5405	R	R2	PJ	18	Square Metre	12/07/2019	6mx3m badly cracked (PV-Digout - Depression (PJ SP))
188378	-34.83501	138.68067	5405	L	L1	FG	2	Metre	28/02/2019	Two posts rotted damaged rail (FR-Safety Barrier (FG SP))
188379	-34.83489	138.68044	5405	R	R1	FB	2	Metre	28/02/2019	Two posts rotted (FB-Safety Barrier (FB RT))
188381	-34.83507	138.68037	5405	R	R1	RR	2	Item	2/07/2019	Take two gums away and poison (MT-Vegetation Control (RR SP))
188385	-34.83444	138.68039	5405	R	R2	RR	1	Item	12/07/2019	Tree trim gum (MT-Vegetation Control (RR SP))
188388	-34.82942	138.67997	5405	R	R2	PN	20	Square Metre	12/07/2019	10mx2m badly cracked (PV-Digout - Depression (PF RT))
188397	-34.80451	138.66438	5405	L	L1	RT	2	Metre	12/07/2019	2m island kerbing (PF-Island Kerb Damaged (RT RT))
188792	-34.81823	138.67727	5405	R	R1	FS	1	Item	5/07/2019	Keep left sign needs replacing (SI-Sign Damaged/Fix (FS SP))
188793	-34.83384	138.6805	5405	L	L1	FS	1	Item	5/07/2019	Keep left sign needs replacing (SI-Sign Damaged/Fix (FS SP))
192061	-34.79213	138.64756	5405	L	L1	ME	2	Item	4/01/2019	Damaged sep lids. Replaced x2 sep lids (EM-Emergency Response (ME RT))
192062	-34.79211	138.64754	5405	L	L1	DR	1	Item	4/01/2019	Double sep concrete frame damaged and centre support pole broken 50m east of main north road next to peter kittle Toyota (DR-Elements Collapsed (DR SP))
192778	-34.79189	138.64731	5405	L	L1	RL	1	Item	15/01/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
192779	-34.79171	138.64726	5405	L	L1	RS	1	Metre	15/01/2019	Sprayed weeds on butterfly (MT-Spraying Required (RS RT))
192780	-34.79157	138.64717	5405	L	L1	RS	1	Metre	15/01/2019	Sprayed weeds on median (MT-Spraying Required (RS RT))
192781	-34.79181	138.64694	5405	L	L1	RS	1	Metre	15/01/2019	Sprayed weeds on median (MT-Spraying Required (RS RT))
193060	-34.79264	138.64845	5405	L	L1	DR	1	Item	17/01/2019	Re-sat SEP lids (DR-Elements Collapsed (DR SP))
193145	-34.79345	138.65007	5405	L	L1	RC	1	Item	18/01/2019	Litter removed from median (AM-Litter / Debris (RC SP))
193153	-34.79444	138.6516	5405	L	L1	RV	1	Item	18/01/2019	Whipper snipped weeds on median (MT-Vegetation Growth (RV RT))
193154	-34.79444	138.6516	5405	L	L1	RS	1	Metre	18/01/2019	Sprayed weeds on median (MT-Vegetation Control (RR SP))
193155	-34.79444	138.6516	5405	L	L1	RC	1	Item	18/01/2019	Litter removed from median (AM-Litter / Debris (RC SP))
193159	-34.79497	138.65226	5405	L	L1	RV	1	Item	18/01/2019	Whipper snipped weeds on median (MT-Vegetation Growth (RV RT))
193160	-34.79497	138.65228	5405	L	L1	RS	1	Metre	18/01/2019	Sprayed weeds on median (MT-Vegetation Control (RR SP))
193168	-34.79594	138.65394	5405	L	L1	RV	1	Item	18/01/2019	Whipper snipped weeds on median (MT-Vegetation Growth (RV RT))
193169	-34.79596	138.65393	5405	L	L1	RS	1	Metre	18/01/2019	Sprayed weeds on median (MT-Vegetation Control (RR SP))
193170	-34.79596	138.65393	5405	L	L1	RC	1	Item	18/01/2019	Litter removed from median (AM-Litter / Debris (RC SP))
193188	-34.80276	138.66237	5405	L	L1	RC	1	Item	18/01/2019	Litter removed from road (AM-Litter / Debris (RC SP))
193189	-34.81108	138.6748	5405	L	L1	RV	1	Item	18/01/2019	Whipper snipped weeds on medians and butterflies (MT-Vegetation Growth (RV RT))
193190	-34.81121	138.67473	5405	L	L1	RS	1	Metre	18/01/2019	Sprayed weeds on medians and butterflies (MT-Vegetation Control (RR SP))
193191	-34.81127	138.67471	5405	L	L1	RL	1	Item	18/01/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))
193193	-34.81339	138.67561	5405	L	L1	FR	1	Item	18/01/2019	Sign corrected (SI-Sign Damaged/Fix (FR RT))
193195	-34.81411	138.67586	5405	L	L1	RL	1	Item	18/01/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
193197	-34.81589	138.67652	5405	L	L1	RL	1	Item	18/01/2019	Removed debris from median (AM-Litter / Debris (RL RT))
193211	-34.81751	138.67704	5405	L	L1	RV	1	Item	18/01/2019	Whipper snipped weeds on medians and butterflies (MT-Vegetation Growth (RV RT))
193212	-34.81753	138.67705	5405	L	L1	RS	1	Metre	18/01/2019	Sprayed weeds on medians and butterflies (MT-Vegetation Control (RR SP))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
193213	-34.81753	138.67705	5405	L	L1	RL	1	Item	18/01/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))
193813	-34.82691	138.67983	5405	L	L1	RT	2	Metre	25/07/2019	Median kerb damaged (PF-Island Kerb Damaged (RT RT))
193818	-34.82696	138.67983	5405	L	L1	ME	1	Item	25/01/2019	Call received on 25/01/19. Damaged median kerb on McIntyre Road near Montague Road. Placed piece back into position and made safe with coldmix (EM-Emergency Response (ME RT))
194018	-34.81178	138.67488	5405	R	R1	RT	1	Metre	24/01/2019	Call received at 6.07pm on 24/01/19. Completed 8.30pm. Broken bullnose on McIntyre Road turning right into the Golden Way. Pushed bullnose back into place and used coldmix to make safe. Removed broken concrete off the road. (PF-Island Kerb Damaged (RT RT))
194174	-34.79838	138.65759	5405	L	L1	FR	1	Item	4/02/2019	Replaced damaged post 80 by 40 (SI-Sign Damaged/Fix (FR RT))
194238	-34.80717	138.66855	5405	L	L1	RM	1	Metre	1/02/2019	Mowing on McIntyre Road between Nelson Road and The Grove Way (MT-Mowing - Growth (RM RT))
194380	-34.79766	138.65659	5405	L	L1	RL	1	Item	5/02/2019	Call received at 2.30pm on 05/02/19. Loose rubble and gravel on McIntyre Road near Bridge Road. Swept off the road and made safe (AM-Litter / Debris (RL RT))
194959	-34.79415	138.65108	5405	L	L1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
194960	-34.79718	138.65589	5405	L	L1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
194961	-34.80202	138.66147	5405	L	L1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
194968	-34.81317	138.67549	5405	R	R1	RT	5	Metre	19/07/2019	Approx. 5m damaged median kerbing and raised bitumen needs repair ASAP (PF-Island Kerb Damaged (RT RT))
194969	-34.81347	138.67561	5405	L	L1	FR	1	Item	13/02/2019	Straightened sign (SI-Sign Damaged/Fix (FR RT))
194970	-34.81515	138.67621	5405	L	L1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
194972	-34.81731	138.67707	5405	L	L1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
194974	-34.81919	138.67776	5405	L	L1	RV	1	Item	13/02/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
194975	-34.81919	138.67777	5405	L	L1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
194977	-34.81944	138.67784	5405	L	L1	RV	1	Item	13/02/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
194979	-34.81942	138.67783	5405	L	L1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
194980	-34.81941	138.67782	5405	L	L1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
194981	-34.82096	138.67835	5405	L	L1	RV	1	Item	13/02/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
194982	-34.82097	138.67834	5405	L	L1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
194983	-34.82143	138.67847	5405	R	R1	RT	6	Metre	19/07/2019	Damaged median kerb approx. 6m (PF-Island Kerb Damaged (RT RT))
194985	-34.82185	138.67861	5405	R	R1	RV	1	Item	13/02/2019	Whipper snipped weeds on median (MT-Vegetation Growth (RV RT))
194986	-34.82247	138.67879	5405	R	R1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
194988	-34.82638	138.67967	5405	R	R1	RV	1	Item	13/02/2019	Whipper snipped weeds on median (MT-Vegetation Growth (RV RT))
194989	-34.8264	138.67966	5405	R	R1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
194990	-34.8264	138.67965	5405	R	R1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
194999	-34.82954	138.6801	5405	R	R1	RV	1	Item	13/02/2019	Whipper snipped weeds on median (MT-Vegetation Growth (RV RT))
195000	-34.82954	138.6801	5405	R	R1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
195001	-34.82954	138.6801	5405	R	R1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
195011	-34.80446	138.66484	5405	L	L1	FS	1	Item	14/02/2019	Sign missing and post bent, both need replacing (SI-Sign Damaged/Fix (FS SP))
195013	-34.82518	138.67925	5405	L	L1	DC	1	Item	13/02/2019	Cleaned out sep drain (DR-Blocked Grid (DC RT))
195016	-34.82436	138.67908	5405	L	L1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
195019	-34.8184	138.67727	5405	R	R1	RV	1	Item	13/02/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
195020	-34.81839	138.67725	5405	R	R1	RS	1	Metre	13/02/2019	Sprayed weeds on median and butterflies (MT-Vegetation Growth (RV RT))
195021	-34.81839	138.67723	5405	R	R1	RL	1	Item	13/02/2019	Removed debris from median and butterflies (AM-Litter / Debris (RL RT))
195023	-34.80436	138.66442	5405	L	L1	FR	1	Item	13/02/2019	Replaced keep right sign and post (SI-Sign Damaged/Fix (FR RT))
195024	-34.80441	138.66444	5405	L	L1	RL	1	Item	13/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
195025	-34.80441	138.66444	5405	L	L1	RS	1	Metre	13/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
195140	-34.79732	138.65601	5405	R	R2	RL	1	Item	5/02/2019	Call received at 8.38pm on 05/02/19. Completed 10.45pm. Gravel and rocks on the corner of McIntyre Road and Bertana Road. Swept and shoveled debris off the road and made safe (AM-Litter / Debris (RL RT))
195185	-34.80657	138.66744	5405	L	L1	FR	1	Item	7/08/2019	ASN lettering falling off - Refer MDR 186992 (SI-Sign Damaged/Fix (FR RT))
196291	-34.81024	138.67421	5405	L	L1	RV	1	Item	28/02/2019	Removed tree branch from bike lane (MT-Vegetation Growth (RV RT))
196292	-34.81046	138.67438	5405	L	L1	DC	1	Item	28/02/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
196315	-34.80288	138.66238	5405	L	L1	RL	1	Item	28/02/2019	Removed debris from road (AM-Litter / Debris (RL RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
196316	-34.80119	138.66046	5405	L	L1	RL	1	Item	28/02/2019	Removed debris from road (AM-Litter / Debris (RL RT))
196318	-34.7952	138.65265	5405	L	L1	RL	1	Item	28/02/2019	Removed debris from median (AM-Litter / Debris (RL RT))
196319	-34.79519	138.65264	5405	L	L1	RS	1	Metre	28/02/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
196346	-34.81181	138.67513	5405	L	L1	PP	1	Item	28/02/2019	1 (PV-Potholes (PP RT))
196347	-34.81181	138.67514	5405	L	L1	RV	1	Item	28/02/2019	Chipped weeds on butterfly (MT-Vegetation Growth (RV RT))
196348	-34.81181	138.67514	5405	L	L1	RS	1	Metre	28/02/2019	Sprayed weeds on butterfly (MT-Vegetation Growth (RV RT))
196349	-34.83368	138.68056	5405	L	L1	RL	1	Item	28/02/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))
196522	-34.80635	138.6671	5405	L	L1	RL	1	Item	4/03/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
197489	-34.83545	138.68059	5405	R	R1	RV	1	Item	14/03/2019	Whipper snipped weeds on median (MT-Vegetation Growth (RV RT))
197490	-34.83545	138.68051	5405	R	R1	RL	1	Item	14/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197491	-34.83538	138.68056	5405	R	R1	RS	1	Metre	14/03/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
197493	-34.83434	138.68041	5405	R	R1	RV	1	Item	14/03/2019	Cut back trees for line of sight (MT-Vegetation Growth (RV RT))
197495	-34.82418	138.67919	5405	L	L1	RL	1	Item	14/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197498	-34.8212	138.67837	5405	L	L1	RL	1	Item	14/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197499	-34.8212	138.67844	5405	L	L1	RS	1	Metre	14/03/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
197502	-34.81166	138.6749	5405	L	L1	RV	1	Item	14/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197503	-34.81166	138.67494	5405	L	L1	PP	3	Item	14/03/2019	3 (PV-Potholes (PP RT))
197543	-34.79773	138.65658	5405	L	L1	RL	1	Item	15/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197546	-34.79276	138.64849	5405	L	L1	FD	1	Item	15/03/2019	Straightened guidepost (PF-Delineator Damaged (FD RT))
197547	-34.78997	138.64356	5405	L	L1	RL	1	Item	15/03/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))
197549	-34.78998	138.64357	5405	L	L1	RV	1	Item	15/03/2019	Chipped weeds on butterfly (MT-Vegetation Growth (RV RT))
197551	-34.78575	138.637	5405	L	L1	RL	1	Item	15/03/2019	Removed debris from road (AM-Litter / Debris (RL RT))
197934	-34.80206	138.66138	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds around signs (MT-Vegetation Growth (RV RT))
197936	-34.80397	138.66389	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds around signs (MT-Vegetation Growth (RV RT))
197938	-34.80649	138.66752	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds around signs (MT-Vegetation Growth (RV RT))
197940	-34.80732	138.66856	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197942	-34.80763	138.6691	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197954	-34.80898	138.67257	5405	R	R1	FR	4	Item	20/03/2019	Replaced 2 x Slippery signs and 2 x When Wet supp plates (SI-Sign Damaged/Fix (FR RT))
197955	-34.80903	138.6725	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds around signs (MT-Vegetation Growth (RV RT))
197961	-34.81599	138.67654	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197964	-34.82046	138.67818	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197965	-34.82049	138.67819	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197966	-34.82167	138.67856	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197970	-34.82225	138.67873	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197975	-34.83013	138.68009	5405	R	R1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197976	-34.82938	138.68003	5405	R	R1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197977	-34.82754	138.67977	5405	R	R1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197978	-34.82753	138.67977	5405	R	R1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197980	-34.82036	138.67807	5405	R	R1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197985	-34.81766	138.67712	5405	R	R1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197986	-34.81766	138.67712	5405	R	R1	RS	1	Metre	20/03/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
197987	-34.81767	138.67716	5405	R	R1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
197988	-34.81634	138.67665	5405	R	R1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
197989	-34.81634	138.67666	5405	R	R1	RS	1	Metre	20/03/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
197990	-34.81632	138.67662	5405	R	R1	RL	1	Item	20/03/2019	Removed debris from road (AM-Litter / Debris (RL RT))
198066	-34.81131	138.67455	5405	R	R1	RL	1	Item	20/03/2019	Removed debris from road (AM-Litter / Debris (RL RT))
198067	-34.80524	138.66587	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from road (AM-Litter / Debris (RL RT))
198069	-34.80523	138.66591	5405	L	L1	RV	1	Item	21/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
198070	-34.80522	138.6659	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
198071	-34.80522	138.6659	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from road (AM-Litter / Debris (RL RT))
198075	-34.79949	138.65879	5405	L	L1	RV	1	Item	20/03/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
198076	-34.79945	138.65882	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
198077	-34.79814	138.65724	5405	L	L1	MG	1	Item	20/03/2019	Removed graffiti (AM-Graffiti Removal (MG RT))
198078	-34.79768	138.65656	5405	L	L1	RL	1	Item	20/03/2019	Removed debris from median (AM-Litter / Debris (RL RT))
198079	-34.79779	138.65695	5405	L	L1	ME	236.5	Item	20/03/2019	Call received at 10.13am on 20/03/19. Concrete spill through the intersection of McIntyre Road and Bridge Road starting in the left hand lane. Sweeper used to clean intersection of concrete (EM-Emergency Response (ME RT))
199461	-34.79248	138.64804	5405	L	L1	RL	1	Item	3/04/2019	Call received at 10.37am on 03/04/19. Dead animal on McIntyre Road near Peacock Road. No dead cat found (AM-Litter / Debris (RL RT))
199490	-34.79369	138.65032	5405	L	L1	RL	1	Item	3/04/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
199494	-34.8099	138.67378	5405	L	L1	RL	1	Item	3/04/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
199498	-34.8338	138.68044	5405	L	L1	RL	1	Item	3/04/2019	Removed rubbish from median and butterflies (AM-Litter / Debris (RL RT))
199500	-34.83391	138.68057	5405	L	L1	RV	1	Item	3/04/2019	Chipped weeds on butterfly (MT-Vegetation Growth (RV RT))
199503	-34.83378	138.68042	5405	L	L1	MG	1	Item	3/04/2019	Removed graffiti from guard rail (AM-Graffiti Removal (MG RT))
199505	-34.82228	138.67856	5405	L	L1	DO	1	Metre	3/04/2019	Removed rubbish from front of sep (DR-Drains Ponding (DO-SP))
199509	-34.80972	138.6734	5405	L	L1	RV	1	Item	3/04/2019	Trim trees for line of sight for 80 km sign (MT-Vegetation Growth (RV RT))
199511	-34.80684	138.66776	5405	L	L1	RL	1	Item	3/04/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
199513	-34.79445	138.65147	5405	L	L1	DR	1	Item	3/04/2019	Re sat sep lids back on (DR-Elements Collapsed (DR SP))
199514	-34.79402	138.65067	5405	L	L1	PP	1	Item	3/04/2019	1 (PV-Potholes (PP RT))
199515	-34.79377	138.65038	5405	L	L1	PP	1	Item	3/04/2019	1 (PV-Potholes (PP RT))
199516	-34.79361	138.65011	5405	L	L1	RL	1	Item	3/04/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
199517	-34.7925	138.64834	5405	L	L1	FR	1	Item	3/04/2019	Whashed no u turn sign (SI-Sign Damaged/Fix (FR RT))
199520	-34.79283	138.64886	5405	L	L1	RL	1	Item	3/04/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
201249	-34.7984	138.65775	5405	L	L1	RL	1	Item	26/04/2019	Removed debris from bike lane (AM-Litter / Debris (RL RT))
202192	-34.82524	138.67927	5405	R	R1	PP	1	Item	8/05/2019	1 (PV-Potholes (PP RT))
202193	-34.82034	138.67804	5405	R	R1	DC	1	Item	8/05/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
202194	-34.81707	138.6769	5405	R	R1	RL	1	Item	8/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
202195	-34.81445	138.67594	5405	R	R1	RL	1	Item	8/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
202196	-34.81324	138.67545	5405	R	R1	DC	1	Item	8/05/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
202197	-34.81317	138.67545	5405	R	R1	RL	1	Item	8/05/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
202228	-34.80884	138.67226	5405	R	R1	RL	1	Item	8/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
202229	-34.80822	138.67055	5405	L	L1	RL	1	Item	8/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
202230	-34.80674	138.6678	5405	L	L1	RL	1	Item	8/05/2019	Removed debris from road (AM-Litter / Debris (RL RT))
202247	-34.79513	138.65255	5405	L	L1	ME	1	Item	8/05/2019	Call received on 08/05/19. Debris on the centre median on McIntyre Road. Checked median between Main North Road and North east Road but no debris on the centre median found (EM-Emergency Response (ME RT))
202250	-34.79254	138.64834	5405	L	L1	DR	1	Item	8/05/2019	Re-sat SEP lid (DR-Elements Collapsed (DR SP))
202251	-34.79251	138.64833	5405	L	L1	FD	1	Item	8/05/2019	Re-stood guidepost (PF-Delineator Damaged (FD RT))
203111	-34.7957	138.6535	5405	L	L1	RL	1	Item	20/05/2019	Removed debris from road (AM-Litter / Debris (RL RT))
203152	-34.79351	138.65007	5405	L	L1	RS	1	Metre	20/05/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
203165	-34.79919	138.65856	5405	L	L1	RS	1	Metre	20/05/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
203166	-34.80266	138.66221	5405	L	L1	RL	1	Item	20/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
203167	-34.80576	138.66684	5405	L	L1	RL	1	Item	20/05/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
203168	-34.81132	138.67492	5405	L	L1	RL	1	Item	20/05/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))
203169	-34.81131	138.67491	5405	L	L1	RV	1	Item	20/05/2019	Chipped weeds on butterfly (MT-Vegetation Growth (RV RT))
203170	-34.81131	138.67491	5405	L	L1	RS	1	Metre	20/05/2019	Sprayed weeds on butterfly (MT-Vegetation Growth (RV RT))
203180	-34.79191	138.647031	5405	L	L1	RL	1	Item	20/05/2019	Removed rubbish from bike lane (AM-Litter / Debris (RL RT))
203181	-34.82153	138.6785	5405	R	R1	RL	1	Item	20/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
203183	-34.82743	138.67986	5405	L	L1	RS	1	Metre	20/05/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
203185	-34.83054	138.68016	5405	R	R1	RS	1	Metre	20/05/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
203189	-34.82905	138.68002	5405	R	R1	PP	2	Item	20/05/2019	2 (PV-Potholes (PP RT))
203190	-34.82819	138.67992	5405	R	R1	RS	1	Metre	20/05/2019	Sprayed weeds on butterflies (MT-Vegetation Growth (RV RT))
203192	-34.82816	138.67988	5405	R	R1	RL	1	Item	20/05/2019	Removed debris from median and road (AM-Litter / Debris (RL RT))
203198	-34.81861	138.67746	5405	R	R1	RS	1	Metre	20/05/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
203202	-34.81506	138.67617	5405	R	R1	RL	1	Item	20/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
203204	-34.81449	138.67599	5405	R	R1	RV	1	Item	20/05/2019	Removed tree branch from median (MT-Vegetation Growth (RV RT))
203205	-34.81381	138.67569	5405	R	R1	RL	1	Item	20/05/2019	Removed debris from median (AM-Litter / Debris (RL RT))
203210	-34.80612	138.66689	5405	R	R1	DC	1	Item	20/05/2019	DR-Blocked Grid (DC RT)
203211	-34.80613	138.6669	5405	R	R1	DC	1	Item	20/05/2019	Removed debris from drain mouth (DR-Blocked Grid (DC RT))
203212	-34.79477	138.65192	5405	R	R1	RS	1	Metre	20/05/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
203754	-34.80848	138.67122	5405	R	R2	PN	19	Square Metre	27/05/2019	19m2 patching (PV-Digout - Depression (PN RT))
203755	-34.811	138.67468	5405	R	R1	PN	12	Square Metre	27/05/2019	12m2 patching (PV-Digout - Depression (PN RT))
203800	-34.79766	138.65658	5405	L	L1	ME	1	Item	27/05/2019	Call received at 9.24sm on 27/05/19. Tree branch on the road on McIntyre Road near Bridge Road. Unable to locate branch on the road (EM-Emergency Response (ME RT))
204546	-34.80886	138.6475	5405	R	R2	PP	10	Item	4/06/2019	10 (PV-Potholes (PP RT))
204564	-34.80268	138.66215	5405	L	L1	RL	1	Item	5/06/2019	Removed debris from road (AM-Litter / Debris (RL RT))
204568	-34.80329	138.66287	5405	L	L1	RL	1	Item	5/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
204569	-34.80655	138.66759	5405	L	L1	RL	1	Item	5/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
204590	-34.83391	138.68041	5405	L	L1	PW	1	Metre	5/06/2019	Swept around butterflies x3 (PV-Pavement Sweeping (PW RT))
204591	-34.83451	138.68052	5405	L	L1	PW	1	Metre	5/06/2019	Swept around butterflies x3 (PV-Pavement Sweeping (PW RT))
204593	-34.83393	138.68044	5405	L	L1	RV	1	Item	5/06/2019	Chipped weeds on medians and butterflies (MT-Vegetation Growth (RV RT))
204595	-34.83459	138.6805	5405	L	L1	RS	1	Metre	5/06/2019	Sprayed weeds on medians and butterflies (MT-Vegetation Growth (RV RT))
204621	-34.83158	138.68009	5405	R	R1	FR	1	Item	5/06/2019	Replaced damaged post on Keep Left Unless Overtaking sign (SI-Sign Damaged/Fix (FR RT))
204623	-34.82866	138.6799	5405	R	R1	RL	1	Item	5/06/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))
204624	-34.82868	138.67994	5405	R	R1	RL	1	Item	5/06/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))
204625	-34.79815	138.6573	5405	L	L1	MG	1	Item	5/06/2019	Removed poster from traffic light (AM-Graffiti Removal (MG RT))
205107	-34.79381	138.6507	5405	L	L1	RS	1	Metre	11/06/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
205110	-34.79584	138.65381	5405	L	L1	RL	1	Item	11/06/2019	Removed debris from road (AM-Litter / Debris (RL RT))
205113	-34.79704	138.65592	5405	L	L1	RS	1	Metre	11/06/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
205116	-34.79548	138.6531	5405	L	L1	RL	1	Item	11/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
205117	-34.79545	138.65311	5405	L	L1	RV	1	Item	11/06/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
205534	-34.79267	138.64838	5405	L	L1	DR	1	Item	14/06/2019	Re-sat SEP lid (DR-Elements Collapsed (DR SP))
205662	-34.81781	138.67732	5405	L	L1	PP	1	Item	17/06/2019	1 (PV-Potholes (PP RT))
205664	-34.83063	138.68017	5405	R	R1	RL	1	Item	17/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
205668	-34.81222	138.67513	5405	R	R1	RL	1	Item	17/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206405	-34.8322	138.68016	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206409	-34.83125	138.68009	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206410	-34.83042	138.68001	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206411	-34.83042	138.68	5405	R	R1	PW	1	Metre	24/06/2019	Removed glass spill from bike lane (PV-Pavement Sweeping (PW RT))
206412	-34.83019	138.67994	5405	R	R1	MG	1	Item	24/06/2019	Removed graffiti from light pole (AM-Graffiti Removal (MG RT))
206415	-34.82711	138.67959	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206416	-34.82601	138.67945	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206417	-34.82606	138.67942	5405	R	R1	RV	1	Item	24/06/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
206418	-34.82606	138.67942	5405	R	R1	RS	1	Metre	24/06/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
206419	-34.82503	138.67926	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206422	-34.82427	138.6791	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206424	-34.82428	138.67908	5405	R	R1	RL	1	Item	24/06/2019	Removed debris from bike lane (AM-Litter / Debris (RL RT))
206428	-34.82302	138.6788	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206429	-34.82215	138.67861	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206432	-34.82118	138.67829	5405	R	R1	DC	1	Item	24/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206433	-34.81907	138.67755	5405	R	R1	RL	1	Item	24/06/2019	Removed debris from road (AM-Litter / Debris (RL RT))
206666	-34.81297	138.67561	5405	L	L1	DC	1	Item	25/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206668	-34.81582	138.67662	5405	L	L1	RV	1	Item	25/06/2019	Cut back trees for line of sight (MT-Vegetation Growth (RV RT))
206670	-34.81619	138.67663	5405	L	L1	RL	1	Item	25/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206671	-34.81675	138.67684	5405	L	L1	RL	1	Item	25/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206672	-34.81759	138.67716	5405	L	L1	RS	1	Metre	25/06/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
206674	-34.8186	138.67747	5405	L	L1	PP	5	Item	25/06/2019	5 (PV-Potholes (PP RT))
206676	-34.8243	138.6794	5405	L	L1	DC	1	Item	25/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206677	-34.82737	138.68	5405	L	L1	RV	1	Item	25/06/2019	Whipper snipped weeds growing between water table and bitumen (MT-Vegetation Growth (RV RT))
206679	-34.82732	138.67997	5405	L	L1	RS	1	Metre	25/06/2019	Sprayed weeds growing between water table and bitumen (MT-Vegetation Growth (RV RT))
206680	-34.82734	138.67993	5405	L	L1	PP	4	Item	25/06/2019	4 (PV-Potholes (PP RT))
206681	-34.82734	138.67993	5405	L	L1	DC	1	Item	25/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206682	-34.83158	138.68041	5405	L	L1	DC	1	Item	25/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206684	-34.81649	138.6767	5405	L	L1	RL	1	Item	25/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206686	-34.81643	138.67655	5405	R	R1	DC	1	Item	25/06/2019	Cleaned drain mouth (DR-Blocked Grid (DC RT))
206687	-34.81049	138.67412	5405	R	R1	RL	1	Item	25/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206688	-34.80465	138.66467	5405	L	L1	RL	1	Item	25/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206690	-34.80279	138.66211	5405	L	L1	RL	1	Item	25/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206698	-34.80068	138.6599	5405	L	L1	ME	1	Item	25/06/2019	Call received at 1.03pm on 25/06/2019. ASN sign had been hit on Nelson Road near McIntyre Road due to motor vehicle accident. Removed damaged post and sign o make safe and logged for repairs. (EM-Emergency Response (ME RT))
206723	-34.79775	138.65658	5405	L	L1	RS	1	Metre	25/06/2019	Sprayed weeds on butterflies (MT-Vegetation Growth (RV RT))
206724	-34.79775	138.65657	5405	L	L1	RL	1	Item	25/06/2019	Removed debris from road (AM-Litter / Debris (RL RT))
206728	-34.7942	138.65113	5405	L	L1	RL	1	Item	25/06/2019	Removed debris from median (AM-Litter / Debris (RL RT))
206828	-34.8043	138.66434	5405	L	L1	RT	1	Metre	26/08/2019	Median kerb pushing out into traffic lane and pushing up bitumen (PF-Island Kerb Damaged (RT RT))
206829	-34.80429	138.66435	5405	L	L1	ME	1	Item	26/06/2019	Call received at 12.23pm on 26/09/2019. Median kerbing had been broken and pushing out onto traffic lane. Moved concrete back inot place and logged for repairs. (EM-Emergency Response (ME RT))
207823	-34.81805	138.67737	5405	L	L1	PP	1	Item	4/07/2019	1 (PV-Potholes (PP RT))
207825	-34.82372	138.6792	5405	L	L1	RL	1	Item	4/07/2019	Removed debris from bike lane (AM-Litter / Debris (RL RT))
208305	-34.81045	138.67434	5405	L	L1	RL	1	Item	10/07/2019	Removed debris from mouth of drain (AM-Litter / Debris (RL RT))
208307	-34.8106	138.67447	5405	L	L1	PW	1	Metre	10/07/2019	Swept gravel from road (PV-Pavement Sweeping (PW RT))
208312	-34.83561	138.68055	5405	R	R1	PP	1	Item	10/07/2019	1 (PV-Potholes (PP RT))
208313	-34.83543	138.68054	5405	R	R1	RL	1	Item	10/07/2019	Removed rubbish from butterfly (AM-Litter / Debris (RL RT))
208326	-34.79894	138.65807	5405	L	L1	DC	1	Item	10/07/2019	Cleaned mouth of drain (DR-Blocked Grid (DC RT))
208329	-34.79591	138.65372	5405	L	L1	RL	1	Item	10/07/2019	Removed rubbish from road (AM-Litter / Debris (RL RT))
208607	-34.79259	138.64834	5405	L	L3	PL	18	Square Metre	15/07/2019	Shoving and lifting asphalt in drive way (PV-Shape - Correction (PL SP))
209553	-34.81142	138.67489	5405	L	L1	PP	1	Item	25/07/2019	1 (PV-Potholes (PP RT))
209554	-34.81781	138.67739	5405	L	L1	PP	1	Item	25/07/2019	1 (PV-Potholes (PP RT))
210297	-34.79211	138.64777	5405	L	L1	RL	1	Item	1/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
210298	-34.7921	138.64774	5405	L	L1	FR	1	Item	1/08/2019	Replaced damaged One Way sign and straightened post (SI-Sign Damaged/Fix (FR RT))
210361	-34.8312	138.68013	5405	R	R1	RS	1	Metre	1/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
210362	-34.82739	138.67975	5405	R	R1	RS	1	Metre	1/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
210363	-34.81867	138.67753	5405	R	R1	RS	1	Metre	1/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
210364	-34.8186	138.67761	5405	L	L1	PP	2	Item	1/08/2019	2 (PV-Potholes (PP RT))
210365	-34.8182	138.67766	5405	R	R1	RS	1	Metre	1/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
210643	-34.81773	138.6771	5405	R	L1	PN	10	Square Metre	8/08/2019	Pn cracking and failing (PV-Digout - Depression (PN RT))
210651	-34.82655	138.67958	5405	R	L2	PN	12	Square Metre	15/08/2019	12m2 depression (PV-Digout - Depression (PN RT))
211230	-34.80641	138.66765	5405	L	L1	FR	1	Item	12/08/2019	Straightened ASN (SI-Sign Damaged/Fix (FR RT))
211234	-34.81807	138.67745	5405	L	L1	RL	1	Item	12/08/2019	Removed debris from butterfly and median (AM-Litter / Debris (RL RT))
211235	-34.81805	138.67744	5405	L	L1	MG	1	Item	12/08/2019	Removed posters from traffic lights (AM-Graffiti Removal (MG RT))
211236	-34.81804	138.67744	5405	L	L1	PP	4	Item	12/08/2019	4 (PV-Potholes (PP RT))
211237	-34.81806	138.67745	5405	L	L1	DC	1	Item	12/08/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
211239	-34.81949	138.67796	5405	L	L1	RL	1	Item	12/08/2019	Removed debris from road (AM-Litter / Debris (RL RT))
211322	-34.81837	138.67725	5405	R	R1	RS	1	Metre	12/08/2019	Sprayed weeds on butterflies (MT-Vegetation Growth (RV RT))
211324	-34.81837	138.67725	5405	R	R1	PP	2	Item	12/08/2019	2 (PV-Potholes (PP RT))
211325	-34.81837	138.67724	5405	R	R1	RL	1	Item	12/08/2019	Removed debris from butterfly (AM-Litter / Debris (RL RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
211337	-34.81412	138.67567	5405	R	R1	DC	1	Item	12/08/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
211341	-34.81304	138.67527	5405	R	R1	RL	1	Item	12/08/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
211345	-34.81308	138.67526	5405	R	R1	RV	1	Item	12/08/2019	Cut back trees from road (MT-Vegetation Growth (RV RT))
211346	-34.81212	138.67492	5405	R	R1	DC	1	Item	12/08/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
211763	-34.8271	138.67988	5405	L	L2	PN	19	Square Metre	15/08/2019	Cracking and failing 19m2 (PV-Digout - Depression (PN RT))
212762	-34.79228	138.64819	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
212763	-34.79228	138.64819	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
212765	-34.7961	138.65408	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
212766	-34.79608	138.65411	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
212770	-34.80981	138.67356	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
212771	-34.80982	138.67357	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
212772	-34.81712	138.67699	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
212774	-34.81772	138.67717	5405	L	L1	PP	2	Item	27/08/2019	2 (PV-Potholes (PP RT))
212775	-34.81774	138.67719	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
212776	-34.81861	138.67754	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
212777	-34.81857	138.67765	5405	L	L1	PP	2	Item	27/08/2019	2 (PV-Potholes (PP RT))
212779	-34.82433	138.67927	5405	L	L1	DC	1	Item	27/08/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
212780	-34.82736	138.67981	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
212782	-34.82888	138.68006	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
212784	-34.82886	138.68005	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on butterflies (MT-Vegetation Growth (RV RT))
212795	-34.82894	138.67997	5405	L	L1	PP	1	Item	27/08/2019	1 (PV-Potholes (PP RT))
212799	-34.83435	138.68054	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on butterflies (MT-Vegetation Growth (RV RT))
212803	-34.83429	138.6806	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from median (AM-Litter / Debris (RL RT))
212855	-34.79831	138.65695	5405	L	L1	RL	1	Item	27/08/2019	Removed debris from butterflies (AM-Litter / Debris (RL RT))
212856	-34.79827	138.65702	5405	L	L1	RS	1	Metre	27/08/2019	Sprayed weeds on butterflies (MT-Vegetation Growth (RV RT))
212857	-34.79829	138.65697	5405	L	L1	MG	1	Item	27/08/2019	Removed posters from traffic light poles (AM-Graffiti Removal (MG RT))
212858	-34.79829	138.65697	5405	L	L1	DC	1	Item	27/08/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
212862	-34.79978	138.65891	5405	L	L1	DC	1	Item	27/08/2019	Re-sat SEP lid (DR-Clear Drain / Lid (DC RT))
212863	-34.79274	138.64861	5405	L	L1	DC	1	Item	27/08/2019	Re-sat SEP lid (DR-Clear Drain / Lid (DC RT))
213502	-34.79461	138.65184	5405	L	L1	RL	1	Item	4/09/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
213762	-34.79815	138.65719	5405	L	L1	RL	1	Item	6/09/2019	Removed debris from median (AM-Litter / Debris (RL RT))
213845	-34.80888	138.67245	5405	L	L2	PN	15	Square Metre	9/09/2019	Pn cracking 15m2 (PV-Digout - Depression (PN RT))
213966	-34.81002	138.6737	5405	R	R1	ME	1	Item	10/09/2019	Call received at 7.29am on 10/09/19. Dead animal on McIntyre Road near the Golden Way. Removed dead kangaroo off the road / Shoulder (EM-Emergency Response (ME RT))
214923	-34.79284	138.64888	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
214924	-34.79515	138.6526	5405	L	L1	RL	2	Item	19/09/2019	2 x Removed debris from road (AM-Litter / Debris (RL RT))
214926	-34.79632	138.65456	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from median (AM-Litter / Debris (RL RT))
214937	-34.79823	138.6576	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214939	-34.799	138.65843	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214940	-34.79978	138.65919	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214942	-34.80141	138.66086	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214943	-34.80393	138.66398	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
214944	-34.80411	138.66434	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214945	-34.80472	138.66522	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214947	-34.80532	138.66623	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214948	-34.80581	138.66685	5405	L	L2	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
214949	-34.80621	138.66734	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214950	-34.80698	138.66828	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214951	-34.80698	138.66828	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from median (AM-Litter / Debris (RL RT))
214952	-34.80719	138.66855	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from bike lane (AM-Litter / Debris (RL RT))
214954	-34.80765	138.66937	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214955	-34.8082	138.67097	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from median (AM-Litter / Debris (RL RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
214958	-34.80948	138.67334	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214959	-34.80971	138.67365	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
214961	-34.812185	138.675287	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214992	-34.81233	138.67538	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214993	-34.81283	138.67555	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214994	-34.81281	138.67553	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
214995	-34.81332	138.67569	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214996	-34.81364	138.67582	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
214998	-34.81422	138.67602	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
215000	-34.81532	138.67646	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
215001	-34.81582	138.67662	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
215015	-34.82019	138.67821	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
215016	-34.82105	138.67837	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from median (AM-Litter / Debris (RL RT))
215017	-34.82559	138.67964	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
215018	-34.83155	138.68027	5405	L	L1	DC	1	Item	19/09/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
215019	-34.83261	138.68023	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from road (AM-Litter / Debris (RL RT))
215020	-34.83148	138.68014	5405	R	R1	MG	1	Item	19/09/2019	Removed poster from light pole (AM-Graffiti Removal (MG RT))
215022	-34.81781	138.67707	5405	R	R1	PP	1	Item	19/09/2019	1 (PV-Potholes (PP RT))
215024	-34.81748	138.67695	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215025	-34.81707	138.6768	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215026	-34.81501	138.67604	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215029	-34.81403	138.67567	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215030	-34.81335	138.6754	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215032	-34.81224	138.67503	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215033	-34.8105	138.67406	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215034	-34.81009	138.67371	5405	R	R1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215035	-34.80833	138.67057	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))
215037	-34.80165	138.66097	5405	L	L1	RL	1	Item	23/09/2019	Removed debris from median (AM-Litter / Debris (RL RT))
215038	-34.80165	138.66097	5405	L	L1	RL	1	Item	19/09/2019	Removed debris from median (AM-Litter / Debris (RL RT))
216594	-34.80404	138.66399	5405	L	L1	ME	1	Item	5/10/2019	Call received on 05/10/19. Dead animal on McIntyre near Nelson Road. Removed dead kangaroo from the median (EM-Emergency Response (ME RT))
216854	-34.79709	138.6559	5405	L	L1	ME	1	Item	10/10/2019	Call received at 3.42pm on 09/10/19. Dead animal at McIntyre and Bridge Road. Removed dead cat from the road (EM-Emergency Response (ME RT))
216855	-34.79768	138.6573	5405	L	L1	MG	1	Item	10/10/2019	Removed posters from traffic lights (AM-Graffiti Removal (MG RT))
216856	-34.80083	138.66011	5405	L	L1	RL	1	Item	10/10/2019	Removed debris from road (AM-Litter / Debris (RL RT))
216857	-34.8052	138.66582	5405	L	L1	RS	1	Metre	10/10/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
216858	-34.80738	138.66867	5405	L	L1	RL	1	Item	10/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
216859	-34.80742	138.6687	5405	L	L1	DC	1	Item	10/10/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
216860	-34.80768	138.66919	5405	L	L1	RL	1	Item	10/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
216861	-34.80769	138.66917	5405	L	L1	DC	1	Item	10/10/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
216862	-34.80815	138.67041	5405	L	L1	RL	1	Item	10/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
216863	-34.80848	138.67139	5405	L	L1	RL	1	Item	10/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
216864	-34.80877	138.67213	5405	R	R1	DC	1	Item	10/10/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
216865	-34.81301	138.67543	5405	L	L1	RL	1	Item	10/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
216866	-34.81351	138.67564	5405	L	L1	RV	1	Item	10/10/2019	Whipper snipped weeds around signpost (MT-Vegetation Growth (RV RT))
216867	-34.81352	138.67562	5405	L	L1	RS	1	Metre	10/10/2019	Sprayed weeds around signpost (MT-Vegetation Growth (RV RT))
216870	-34.81695	138.6769	5405	L	L1	PP	1	Item	10/10/2019	1 (PV-Potholes (PP RT))
216872	-34.81776	138.67718	5405	L	L1	RV	1	Item	10/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))
216873	-34.81738	138.67704	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216882	-34.81828	138.67723	5405	L	L1	RS	1	Metre	10/10/2019	Sprayed weeds on butterfly (MT-Vegetation Growth (RV RT))
216883	-34.81811	138.67746	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216885	-34.81756	138.67709	5405	L	L1	RV	1	Item	10/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
216886	-34.82033	138.67814	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216887	-34.82084	138.67831	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216888	-34.82239	138.67877	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216889	-34.8262	138.67965	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216890	-34.8262	138.67965	5405	L	L1	RV	1	Item	10/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))
216896	-34.82878	138.68004	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216898	-34.8288	138.68002	5405	L	L1	RV	1	Item	10/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))
216899	-34.82847	138.67981	5405	L	L1	RS	1	Metre	10/10/2019	Sprayed weeds around butterfly islands (MT-Vegetation Growth (RV RT))
216900	-34.82949	138.68005	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216901	-34.83097	138.68022	5405	L	L1	RV	1	Item	10/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))
216902	-34.83036	138.68014	5405	L	L1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216903	-34.8331	138.68041	5405	L	L1	RV	1	Item	10/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))
216905	-34.83143	138.68026	5405	L	L1	RS	1	Metre	10/10/2019	Sprayed weeds around signpost (MT-Vegetation Growth (RV RT))
216906	-34.83248	138.68039	5405	L	L1	RV	1	Item	10/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))
216912	-34.83455	138.68051	5405	R	R1	RS	1	Metre	10/10/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
216916	-34.82539	138.67928	5405	R	R1	RL	1	Item	10/10/2019	Removed rubbish from road (AM-Litter / Debris (RL RT))
216917	-34.82181	138.67846	5405	R	R1	RL	1	Item	10/10/2019	Removed rubbish from road (AM-Litter / Debris (RL RT))
216918	-34.82114	138.67824	5405	R	R1	RL	1	Item	10/10/2019	Removed rubbish from road (AM-Litter / Debris (RL RT))
216920	-34.81944	138.67765	5405	R	R1	RL	1	Item	10/10/2019	Removed rubbish from road (AM-Litter / Debris (RL RT))
216921	-34.81943	138.67764	5405	R	R1	DC	1	Item	10/10/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
216925	-34.81493	138.67615	5405	R	R1	RV	1	Item	10/10/2019	Whipper sniped weeds around signpost (MT-Vegetation Growth (RV RT))
216926	-34.81493	138.67615	5405	R	R1	RS	1	Metre	10/10/2019	Sprayed weeds around signpost (MT-Vegetation Growth (RV RT))
216927	-34.81496	138.67615	5405	R	R1	RL	1	Item	10/10/2019	Removed rubbish from median (AM-Litter / Debris (RL RT))
216929	-34.81291	138.67537	5405	R	R1	RV	1	Item	10/10/2019	Whipper sniped weeds around signpost (MT-Vegetation Growth (RV RT))
216931	-34.81291	138.67537	5405	R	R1	RS	1	Metre	10/10/2019	Sprayed weeds around signpost (MT-Vegetation Growth (RV RT))
217305	-34.79726	138.65608	5405	L	L1	RV	1	Item	15/10/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
217306	-34.79727	138.65608	5405	L	L1	RS	1	Metre	15/10/2019	Sprayed weeds on median (MT-Vegetation Growth (RV RT))
217307	-34.79728	138.65606	5405	L	L1	RL	1	Item	15/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
217315	-34.80485	138.66519	5405	L	L1	RM	1	Metre	10/10/2019	Mowing on McIntyre Road between Bridge Road and Milne Street (MT-Mowing (RM RT))
218058	-34.79347	138.64994	5405	L	L1	DC	1	Item	24/10/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
218059	-34.79347	138.64994	5405	L	L1	RV	1	Item	24/10/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
218060	-34.79347	138.64994	5405	L	L1	RS	1	Metre	24/10/2019	Sprayed weeds on median (MT-Herbicide Spraying (RS RT))
218061	-34.79347	138.64994	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218067	-34.7948	138.652	5405	L	L1	RV	1	Item	24/10/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
218068	-34.7948	138.652	5405	L	L1	RS	1	Metre	24/10/2019	Sprayed weeds on median (MT-Herbicide Spraying (RS RT))
218069	-34.7948	138.652	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218075	-34.79597	138.65391	5405	L	L1	RV	1	Item	24/10/2019	Whipper sniped weeds on median (MT-Vegetation Growth (RV RT))
218076	-34.79597	138.65391	5405	L	L1	RS	1	Metre	24/10/2019	Sprayed weeds on median (MT-Herbicide Spraying (RS RT))
218077	-34.79597	138.65391	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218081	-34.8008	138.66014	5405	L	L1	PP	3	Item	24/10/2019	3 (PV-Potholes (PP RT))
218082	-34.80109	138.66039	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218084	-34.804	138.66395	5405	L	L1	RV	1	Item	24/10/2019	Chipped weeds around sign (MT-Vegetation Growth (RV RT))
218085	-34.80548	138.66623	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218086	-34.8075	138.66886	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218087	-34.80796	138.66986	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218090	-34.80856	138.67164	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218091	-34.809	138.6725	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218092	-34.809	138.6725	5405	L	L1	RS	1	Metre	24/10/2019	Sprayed weeds around sign (MT-Herbicide Spraying (RS RT))
218137	-34.82722	138.67981	5405	L	L1	RS	1	Metre	24/10/2019	Sprayed weeds on median (MT-Herbicide Spraying (RS RT))
218145	-34.83304	138.6804	5405	L	L1	RS	1	Metre	24/10/2019	Sprayed weeds on median (MT-Herbicide Spraying (RS RT))
218148	-34.82802	138.67991	5405	R	R1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218149	-34.82689	138.67972	5405	R	R1	RL	1	Item	24/10/2019	Removed debris from shoulder (AM-Litter / Debris (RL RT))

job number	latitude	longitude	road no	cway code	lane code	activity code	quantity	units	date	comments
218152	-34.82531	138.67944	5405	R	R1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218153	-34.82392	138.67913	5405	R	R1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218154	-34.82333	138.679	5405	R	R1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218159	-34.81701	138.67687	5405	R	R1	RV	1	Item	24/10/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
218161	-34.81701	138.67687	5405	R	R1	RS	1	Metre	24/10/2019	Sprayed weeds on median (MT-Herbicide Spraying (RS RT))
218163	-34.8124	138.6752	5405	R	R1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218164	-34.80977	138.67357	5405	R	R1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218169	-34.80688	138.66795	5405	L	L1	DC	1	Item	24/10/2019	Cleared drain mouth (DR-Clear Drain / Lid (DC RT))
218170	-34.80582	138.66667	5405	L	L1	RL	1	Item	25/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218172	-34.80582	138.66666	5405	L	L1	RL	1	Item	24/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218173	-34.80431	138.66437	5405	L	L1	RV	1	Item	24/10/2019	Chipped weeds on median (MT-Vegetation Growth (RV RT))
218293	-34.79459	138.65195	5405	L	L1	RL	1	Item	25/10/2019	Removed debris from median (AM-Litter / Debris (RL RT))
218294	-34.79584	138.65391	5405	L	L1	RL	1	Item	25/10/2019	Removed concrete from kerb (AM-Litter / Debris (RL RT))

RELEASED UNDER FOIA

Inspection	Inspection Date	Officer Name	Site Name	Road ID	Feature
PatrolCentral Fortnightly Loop	5/06/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	19/06/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
Ad Hoc Inspection	24/05/2019		MCINTYRE RD (5405)	108701	WSR-Whole Site Road
Ad Hoc Inspection	24/05/2019		MCINTYRE RD RIGHT (5405)	2000080	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	30/01/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
Ad Hoc Inspection	4/06/2019	Patrol East	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	3/07/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	17/07/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	1/08/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	12/08/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	27/08/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	6/09/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	19/09/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	10/10/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	25/10/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	13/02/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	28/02/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	13/03/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	27/03/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	10/04/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
Ad Hoc Inspection	15/07/2019		MCINTYRE RD (5405)	108701	WSR-Whole Site Road
Ad Hoc Inspection	25/07/2019		MCINTYRE RD RIGHT (5405)	2000080	WSR-Whole Site Road
Ad Hoc Inspection	5/08/2019		MCINTYRE RD RIGHT (5405)	2000080	WSR-Whole Site Road
Ad Hoc Inspection	15/08/2019		MCINTYRE RD LEFT (5405)	2000023	WSR-Whole Site Road
Ad Hoc Inspection	26/08/2019		MCINTYRE RD (5405)	108701	WSR-Whole Site Road
Ad Hoc Inspection	26/08/2019		MCINTYRE RD RIGHT (5405)	2000080	WSR-Whole Site Road
Ad Hoc Inspection	9/09/2019		MCINTYRE RD LEFT (5405)	2000023	WSR-Whole Site Road
Ad Hoc Inspection	23/09/2019	Patrol Gawler	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	26/04/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	9/05/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
Ad Hoc Inspection	23/05/2019		MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	23/05/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
Ad Hoc Inspection	3/11/2019	Patrol East	MCINTYRE RD LEFT (5405)	2000023	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	6/11/2019	Patrol Central	MCINTYRE RD (5405)	108801	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	5/06/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	19/06/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	3/07/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	17/07/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	1/08/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	12/08/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	27/08/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	6/09/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	19/09/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	10/10/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	25/10/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road
PatrolCentral Fortnightly Loop	6/11/2019	Patrol Central	MCINTYRE RD (5405)	108701	WSR-Whole Site Road

PART	ASSET ELEMENT	TASK DESCRIPTION	MAINTENANCE CODE	
			ROUTINE	SPECIFIC
110M	Trenches	Excavation Or Trenching By Others		TR
811	Drainage	Scour Repair		SS
811	Drainage	Clear Drainage Elements	DC	DR
811	Drainage	Clear Open Drains and Lined Drains	DD	DO
811	Drainage	Clear Subsoil Drains	DS	
812	Pavement	Crack Sealing	PF	PK
812	Pavement	Pothole Repair	PP	
812	Pavement	Pavement Sweeping	PW	
812	Pavement	Local Shape Correction	PC	PL
812	Pavement	Edge Break Repair	PE	
812	Pavement	Pavement Digouts	PN	PJ
812	Pavement	Repairs to Bituminous Surfacing	PS	PT
812	Pavement	Traffic Island Maintenance	RT	RI
812	Pavement	Low Castings		LC
813	Unsealed Surface	Unsealed Surface	SG	
813	Unsealed Surface	Resheeting Unsealed Surfaces		SR
814	Roadside Furniture	Safety Barrier	FB	FG
814	Roadside Furniture	Wire Rope	WR	WG
814	Roadside Furniture	Fence	RF	RB
814	Roadside Furniture	Maintenance Installation & Replacement of Delineators	FD	FP
814	Roadside Furniture	Maintenance Installation & Replacement of Signs	FR	FS
815	Roadside Vegetation	Mowing	RM	
815	Roadside Vegetation	Herbicide Treatment	RS	
815	Roadside Vegetation	Vegetation Control	RV	RR
816	Amenity	Road User Amenity Maintenance	RA	RP
816	Amenity	Litter Collection	RL	RC
817	Miscellaneous	Reporting Accident Damage and Vand	MA	
817	Miscellaneous	Emergency Response	ME	
817	Miscellaneous	Graffiti Removal	MG	