

SAFETY ALERT

Incident Title:

Damaged Power Board

Date of Incident:

June 2016

Incident Description and Details:

A damaged power board was found which was identified as an electrical hazard. A contractor was engaged by the to conduct electrical testing and tagging of all appliances on the site.

Recommendations/Lessons:

- The electrical item was deemed dangerous, tagged as a **"DO NOT USE"** item and removed.
- If you see any electrical items that look damaged, remove the item so it can no longer be used and immediately report the hazard.

